JOURNEY PLAN - Rhovan to Lichtenburg

Prepared by freightXchange

ROUTE DESCRIPTION	ROUTE HAZARDS		MAP KEYS			
Rhovan Vanadium Mine Head southwest on Rhovan Entrance toward R556 - 2.7km Turn left onto R556 - 18.8km	Pedestrians		Railway	À	Pedestrians	
		1	Animals	WEIGH BRIDGE	Weigh Bridge	
Turn right to merge onto N4 - 58.9km Turn left onto R52 - 38.7km Turn right onto Brook St - 180m Turn right onto R52 - 82.2km	Koster weighbridge Pedestrians		Poor Visibility		Slippery Road	
Turn right - 1.7km	Railway crossing just before Lichtenburg.		Potholes		Gas Station	
Turn left - 600m Lafarge Cement Lichtenburg Plant	Drivers to drive slowly through Lichtenburg town and adhere to all speed limits and road signs. Be on the lookout for pedestrians at intersections. Be cautious for vehicles entering and entering the Lafarge Plant. Lafarge weighbridge	R	Road Works	神术	Children	
	200,50 10,512,050		Falling Rocks	REST	Rest Stop	

