


JOURNEY PLAN - Lichtenburg to Nelspruit

Prepared by **freightXchange**
REDEFINING LOGISTICS


ROUTE DESCRIPTION	ROUTE HAZARDS	MAP KEYS
Lafarge Cement Lichtenburg Plant - head South Turn right - 1.7 km Turn left onto R52 - 82.2 km Turn left onto Brook St - 180 m Turn left onto R52 - 38.7 km	Railway crossing just before Lichtenburg. Drivers to drive slowly through Lichtenburg town and adhere to all speed limits and road signs. Be on the lookout for pedestrians and farm animals crossing the road. Be cautious for vehicles entering and exiting the Lafarge Plant. Road markings not visible. Practise extreme caution when traveling at night times, the road is very dark and full of uneven surfaces and potholes.	 Railway  Pedestrians  Animals  Weigh Bridge  Poor Visibility  Slippery Road  Potholes  Poor Visibility  Road Works  Children  Falling Rocks  Rest Stop
Turn right onto N4 - 122 km Use any lane to merge onto N1/N4 toward Jhb/Pretoria/Witbank - 11.8km Use the left 2 lanes to take exit 145 to merge onto N4 toward Witbank - 219 km Take the exit toward R36 - 550 m Continue onto R36 - 15.3 km	Beware of pedestrians and stray animals in the Bapon area. Early mornings and late afternoons mist and fog may appear which make visibility very poor on the N4 from Rustenburg to Middelburg. Drivers to exercise caution at all Tollgate areas for pedestrians and other vehicles.	
Continue onto R539 - 14.8 km Continue straight to stay on R539 - 30.8 km Turn left onto N4 - 23.2 km Use the left lane to take the ramp to R104 - 1.3 km Continue onto R104 - 5.5 km Continue onto Samore Machel Dr/R104 - 160 m	Early morning fog is a major problem which could result in temporary road closures. Drivers to be cautious when moving through Waterval Boven - up and down hills. Drivers to be cautious of following vehicles - Hijacking area.	



JOURNEY PLAN - Lichtenburg to Hazyview


Prepared by **freightXchange**
REDEFINING LOGISTICS

ROUTE DESCRIPTION	ROUTE HAZARDS	MAP KEYS
Lafarge Cement Lichtenburg Plant - head South Turn right - 1.7 km Turn left onto R52 - 82.2 km Turn left onto Brook St - 180 m Turn left onto R52 - 38.7 km	Railway crossing just before Lichtenburg. Drivers to drive slowly through Lichtenburg town and adhere to all speed limits and road signs. Be on the lookout for pedestrians and farm animals crossing the road. Be cautious for vehicles entering and exiting the Lafarge Plant. Road markings not visible. Practise extreme caution when traveling at night times, the road is very dark and full of uneven surfaces and potholes.	 Railway  Pedestrians  Animals  Weigh Bridge  Poor Visibility  Slippery Road  Potholes  Poor Visibility  Road Works  Children  Falling Rocks  Rest Stop
Turn right onto N4 - 122 km Use any lane to merge onto N1/N4 toward Jhb/Pretoria/Witbank - 11.8km Use the left 2 lanes to take exit 145 to merge onto N4 toward Witbank - 219 km Take the exit toward R36 - 550 m Continue onto R36 - 15.3 km	Beware of pedestrians and stray animals in the Bapon area. Early mornings and late afternoons mist and fog may appear which make visibility very poor on the N4 from Rustenburg to Middelburg. Drivers to exercise caution at all Tollgate areas for pedestrians and other vehicles.	
Continue onto R539 - 14.8 km Continue straight to stay on R539 - 30.8 km Turn left onto N4 - 27.2 km, Take the exit - 230 m Take Provincial P9/2 Rd/R40 and R538 to your destination in Hazyview	Early morning fog is a major problem which could result in temporary road closures. Drivers to be cautious when moving through Waterval Boven - up and down hills. Drivers to be cautious of following vehicles - Hijacking area. Be cautious for stray farm animals and pedestrians.	



JOURNEY PLAN - Lichtenburg to Kabokweni


ROUTE DESCRIPTION	ROUTE HAZARDS	MAP KEYS
Lafarge Cement Lichtenburg Plant - head South Turn right - 1.7 km Turn left onto R52 - 82.2 km Turn left onto Brook St - 180 m Turn left onto R52 - 38.7 km	Railway crossing just before Lichtenburg. Drivers to drive slowly through Lichtenburg town and adhere to all speed limits and road signs. Be on the lookout for pedestrians and farm animals crossing the road. Be cautious for vehicles entering and exiting the Lafarge Plant. Road markings not visible. Practise extreme caution when traveling at night times, the road is very dark and full of uneven surfaces and potholes.	Railway Animals Poor Visibility Potholes Road Works Falling Rocks Pedestrians Weigh Bridge Slippery Road Poor Visibility Children Rest Stop
Turn right onto N4 - 122 km Use any lane to merge onto N1/N4 toward Jhb/Pretoria/Witbank - 11.8km Use the left 2 lanes to take exit 145 to merge onto N4 toward Witbank - 219 km Take the exit toward R36 - 550 m Continue onto R36 - 15.3 km	Beware of pedestrians and stray animals in the Bapon area. Early mornings and late afternoons mist and fog may appear which make visibility very poor on the N4 from Rustenburg to Middelburg. Drivers to exercise caution at all Tollgate areas for pedestrians and other vehicles.	
Continue onto R539 - 14.8 km Continue straight to stay on R539 - 30.8 km Turn left onto N4 - 27.2 km, Take the exit - 230 m Take Provincial P9/2 Rd/R40 and R538 to your destination in Kabokweni	Early morning fog is a major problem which could result in temporary road closures. Drivers to be cautious when moving through Waterval Boven - up and down hills. Drivers to be cautious of following vehicles - Hijacking area. Be cautious for stray farm animals and pedestrians.	



JOURNEY PLAN - Lichtenburg to Kanyamazane


Prepared by **freightXchange**
REDEFINING LOGISTICS

ROUTE DESCRIPTION	ROUTE HAZARDS	MAP KEYS
Lafarge Cement Lichtenburg Plant - head South Turn right - 1.7 km Turn left onto R52 - 82.2 km Turn left onto Brook St - 180 m Turn left onto R52 - 38.7 km	Railway crossing just before Lichtenburg. Drivers to drive slowly through Lichtenburg town and adhere to all speed limits and road signs. Be on the lookout for pedestrians and farm animals crossing the road. Be cautious for vehicles entering and exiting the Lafarge Plant. Road markings not visible. Practise extreme caution when traveling at night times, the road is very dark and full of uneven surfaces and potholes.	 Railway  Pedestrians  Animals  Weigh Bridge  Poor Visibility  Slippery Road  Potholes  Poor Visibility  Road Works  Children  Falling Rocks  Rest Stop
Turn right onto N4 - 122 km Use any lane to merge onto N1/N4 toward Jhb/Pretoria/Witbank - 11.8km Use the left 2 lanes to take exit 145 to merge onto N4 toward Witbank - 219 km Take the exit toward R36 - 550 m Continue onto R36 - 15.3 km	Beware of pedestrians and stray animals in the Bapon area. Early mornings and late afternoons mist and fog may appear which make visibility very poor on the N4 from Rustenburg to Middelburg. Drivers to exercise caution at all Tollgate areas for pedestrians and other vehicles.	
Continue onto R539 - 14.8 km Continue straight to stay on R539 - 30.8 km Turn left onto N4 - 53.1 km Continue on Swan St. Take Chris Hani St to Hercules St in Kanyamazane-A, Kanyamazane	Early morning fog is a major problem which could result in temporary road closures. Drivers to be cautious when moving through Waterval Boven - up and down hills. Drivers to be cautious of following vehicles - Hijacking area.	



JOURNEY PLAN - Lichtenburg to Luphisi


ROUTE DESCRIPTION	ROUTE HAZARDS	MAP KEYS
Lafarge Cement Lichtenburg Plant - head South Turn right - 1.7 km Turn left onto R52 - 82.2 km Turn left onto Brook St - 180 m Turn left onto R52 - 38.7 km	Railway crossing just before Lichtenburg. Drivers to drive slowly through Lichtenburg town and adhere to all speed limits and road signs. Be on the lookout for pedestrians and farm animals crossing the road. Be cautious for vehicles entering and exiting the Lafarge Plant. Road markings not visible. Practise extreme caution when traveling at night times, the road is very dark and full of uneven surfaces and potholes.	Railway Animals Poor Visibility Potholes Road Works Falling Rocks Pedestrians Weigh Bridge Slippery Road Poor Visibility Children Rest Stop
Turn right onto N4 - 122 km Use any lane to merge onto N1/N4 toward Jhb/Pretoria/Witbank - 11.8km Use the left 2 lanes to take exit 145 to merge onto N4 toward Witbank - 219 km Take the exit toward R36 - 550 m Continue onto R36 - 15.3 km	Beware of pedestrians and stray animals in the Bapon area. Early mornings and late afternoons mist and fog may appear which make visibility very poor on the N4 from Rustenburg to Middelburg. Drivers to exercise caution at all Tollgate areas for pedestrians and other vehicles.	
Continue onto R539 - 14.8 km Continue straight to stay on R539 - 30.8 km Turn left onto N4 - 42.8 km Continue on R538 Take Mohlala Dr to Luphisi Dr in Luphisi	Early morning fog is a major problem which could result in temporary road closures. Drivers to be cautious when moving through Waterval Boven - up and down hills. Drivers to be cautious of following vehicles - Hijacking area.	



JOURNEY PLAN - Lichtenburg to Mkhuhlu

Prepared by **freightXchange**
REDEFINING LOGISTICS

ROUTE DESCRIPTION	ROUTE HAZARDS	MAP KEYS
Lafarge Cement Lichtenburg Plant - head South Turn right - 1.7 km Turn left onto R52 - 82.2 km Turn left onto Brook St - 180 m Turn left onto R52 - 38.7 km	Railway crossing just before Lichtenburg. Drivers to drive slowly through Lichtenburg town and adhere to all speed limits and road signs. Be on the lookout for pedestrians and farm animals crossing the road. Be cautious for vehicles entering and exiting the Lafarge Plant. Road markings not visible. Practise extreme caution when traveling at night times, the road is very dark and full of uneven surfaces and potholes.	 Railway  Pedestrians  Animals  Weigh Bridge  Poor Visibility  Slippery Road  Potholes  Poor Visibility  Road Works  Children  Falling Rocks  Rest Stop
Turn right onto N4 - 122 km Use any lane to merge onto N1/N4 toward Jhb/Pretoria/Witbank - 11.8km Use the left 2 lanes to take exit 145 to merge onto N4 toward Witbank - 219 km Take the exit toward R36 - 550 m Continue onto R36 - 15.3 km	Beware of pedestrians and stray animals in the Bapon area. Early mornings and late afternoons mist and fog may appear which make visibility very poor on the N4 from Rustenburg to Middelburg. Drivers to exercise caution at all Tollgate areas for pedestrians and other vehicles.	
Continue onto R539 - 14.8 km Continue straight to stay on R539 - 30.8 km Turn left onto N4 - 27.2 km Take the exit - 230m Follow R40 and R536 to your destination in Mkhuhlu-A, Mkhuhlu	Early morning fog is a major problem which could result in temporary road closures. Drivers to be cautious when moving through Waterval Boven - up and down hills. Drivers to be cautious of following vehicles - Hijacking area.	



JOURNEY PLAN - Lichtenburg to White River

Prepared by **freightXchange**
REDEFINING LOGISTICS

ROUTE DESCRIPTION	ROUTE HAZARDS	MAP KEYS
Lafarge Cement Lichtenburg Plant - head South Turn right - 1.7 km Turn left onto R52 - 82.2 km Turn left onto Brook St - 180 m Turn left onto R52 - 38.7 km	Railway crossing just before Lichtenburg. Drivers to drive slowly through Lichtenburg town and adhere to all speed limits and road signs. Be on the lookout for pedestrians and farm animals crossing the road. Be cautious for vehicles entering and exiting the Lafarge Plant. Road markings not visible. Practise extreme caution when traveling at night times, the road is very dark and full of uneven surfaces and potholes.	 Railway  Pedestrians  Animals  Weigh Bridge  Poor Visibility  Slippery Road  Potholes  Poor Visibility  Road Works  Children  Falling Rocks  Rest Stop
Turn right onto N4 - 122 km Use any lane to merge onto N1/N4 toward Jhb/Pretoria/Witbank - 11.8km Use the left 2 lanes to take exit 145 to merge onto N4 toward Witbank - 219 km Take the exit toward R36 - 550 m Continue onto R36 - 15.3 km	Beware of pedestrians and stray animals in the Bapon area. Early mornings and late afternoons mist and fog may appear which make visibility very poor on the N4 from Rustenburg to Middelburg. Drivers to exercise caution at all Tollgate areas for pedestrians and other vehicles.	
Continue onto R539 - 14.8 km Continue straight to stay on R539 - 30.8 km Turn left onto N4 - 27.2 km Take the exit - 230m Drive to Chief Mgiyeni Khumalo Dr/R40 in White River	Early morning fog is a major problem which could result in temporary road closures. Drivers to be cautious when moving through Waterval Boven - up and down hills. Drivers to be cautious of following vehicles - Hijacking area.	

